

∅ D mm	L mm	I mm	MORSE	Počet zubů
9,8	168	38	1	4
10 H11	168	38	1	4
10,75	175	41	1	4
11 H11	175	41	1	4
11,75	182	44	1	4
12 H11	182	44	1	4
12,75	182	44	1	4
13 H11	182	44	1	4
13,75	189	47	1	4
14 H11	189	47	1	4
14,75	204	50	2	4
15 H11	204	50	2	4
15,75	210	52	2	4
16 H11	210	52	2	4
16,75	214	54	2	4
17 H11	214	54	2	4
17,75	219	56	2	4
18 H11	219	56	2	4
18,70	223	58	2	4
19 H11	223	58	2	4
19,70	228	60	2	4
20 H11	228	60	2	4
20,70	232	62	2	4
21 H11	232	62	2	4
21,70	237	64	2	4
22 H11	237	64	2	4
22,70	241	66	2	4
23 H11	241	66	2	4
23,70	268	68	3	4
24 H11	268	68	3	4
24,70	268	68	3	4
25 H11	268	68	3	4
25,70	273	70	3	4
26 H11	273	70	3	4
27,70	277	71	3	4
28 H11	277	71	3	4
29,70	281	73	3	4
30 H11	281	73	3	4
31,60	317	77	4	4
32 H11	317	77	4	4

Vysvětlivky:

∅ D= průměr nástroje

L= celková délka

I= délka řezné části

